



| | | | |
|---|---------------------------|---|------------------------------------|
| DATE 2015-07-21 | TECHNICIAN Darren Mann | JOB/ORDER # 5034 | REFERENCE TEXT Client reference |
| FIRST NAME Rodel | LAST NAME Flores | | |
| BILLING ADDRESS COMPANY / BILLING NAME 1330 HORNBY ST. VANCOUVER, V6Z1W5 BRITISH COLUMBIA, CANADA | | SERVICE ADDRESS #303 - 1330 HORNBY ST., BUZZER #020 VANCOUVER, V6Z1W5 BRITISH COLUMBIA, CANADA | |
| PHONE 6047603118 | | EMAIL emzledor@gmail.com | |

REASON FOR TODAY'S CALL:
 -leak under kitchen sink, believed to be coming from drainage.

DESCRIPTION OF WORK PERFORMED:
 The kitchen sink strainer assembly was rusted out and leaking. I replaced the strainer assembly and tested by filling and draining the sink.

| QTY. | CODE | DESCRIPTION | UNIT PRICE | PRICE |
|-----------|------|-------------------------|------------|----------|
| 1 | | Replace Basket Strainer | \$159.00 | \$159.00 |
| SUBTOTAL: | | | | \$159.00 |
| GST (5%): | | | | \$7.95 |
| TOTAL: | | | | \$166.95 |

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2015-07-21

CUSTOMER SIGNATURE

DATE