



DATE 2015-07-29	TECHNICIAN Darren Mann	JOB/ORDER # 5067	REFERENCE TEXT Client reference
FIRST NAME Lincoln	LAST NAME Crichlow		
BILLING ADDRESS COMPANY / BILLING NAME 1001 - 989 BEATTY STREET VANCOUVER, V6Z 3C2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #1001 - 989 BEATTY STREET BUZ#2001 TENANT: 604.355.3818 LINCOLN: 646.385.5810 VANCOUVER, V6Z 3C2 BRITISH COLUMBIA, CANADA	
PHONE 3473272668	EMAIL lincolncrichlow@gmail.com		

REASON FOR TODAY'S CALL:
lavatory faucet missing aerator. Spraying irratically.

DESCRIPTION OF WORK PERFORMED:
The existing aerator in the lavatory faucet broke apart and fell out. I installed a new aerator and tested.

TECHNICIAN RECOMMENDATIONS:
The water pressure coming out of the lavatory faucet seems to be quite high. I left an extra aerator with the tenant in the case that this happens again.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Lav Faucet Aerator	\$109.00	\$109.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45

_____ 2015-07-29
 CUSTOMER SIGNATURE DATE