



DATE 2015-08-04	TECHNICIAN Darren Mann	JOB/ORDER # 5094	REFERENCE TEXT Client reference
FIRST NAME Vera		LAST NAME Sal	
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B 2T4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1601 - 989 NELSON ST BUZ#179 LINDA: 604.966.4711 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.980.9100		EMAIL vera@rentitfurnished.com	

REASON FOR TODAY'S CALL:
-no water coming out of shower

DESCRIPTION OF WORK PERFORMED:
The shower valve cartridge broke internally. I replaced this cartridge with new and tested. I also removed hair from the tub drain.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Single Cartridge - Moen	\$129.00	\$129.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$129.00
GST (5%):	\$6.45
TOTAL:	\$135.45

_____ 2015-08-04
 CUSTOMER SIGNATURE DATE