



DATE 2015-09-24	TECHNICIAN Darren Mann	JOB/ORDER # 5324	REFERENCE TEXT Client reference
FIRST NAME Lynden		LAST NAME Wei	
BILLING ADDRESS DUNOWEN PROPERTIES 201 - 1288 ALBERNI STREET VANCOUVER, V6E 4N5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1005 - 1077 MARINASIDE CRESCENT, BUZ#1561 TENANT: 778.323.6615 778.737.9449 VANCOUVER, V6Z 2Z5 BRITISH COLUMBIA, CANADA	
PHONE 778.919.9810		EMAIL operations@dunowen.com	

REASON FOR TODAY'S CALL:

Toilet tank leaking from connector. Tenant bought a new connector. Attachment assistance required plus check to make sure issue is resolved.

DESCRIPTION OF WORK PERFORMED:

-I replaced the toilet supply line and during testing noticed the flapper was warped and the fillvalve was struggling to fill the tank. I replaced the fillvalve and flapper tested again and the toilet is now in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet Fill-Valve, Flapper, Supply - Standard	\$169.00	\$169.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$169.00
GST (5%):	\$8.45
TOTAL:	\$177.45

_____ 2015-09-24

 CUSTOMER SIGNATURE DATE