



HST #837181627

DATE 2015-10-16	TECHNICIAN Darren Mann		JOB/ORDER # 5398	REFERENCE TEXT Client reference
FIRST NAME Lorna		LAST NAME Hawes		
BILLING ADDRESS COMPANY / BILLING NAME 602 - 456 MOBERLY ROAD VANCOUVER, V5Z 4L7 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 602 - 456 MOBERLY BUZZER: 3087 VANCOUVER, V5Z 4 BRITISH COLUMBIA	ROAD
PHONE 604-879-4425			EMAIL ljhawes@telus.net	

REASON FOR TODAY'S CALL:

Complete toilet flapper structure needs replacing. Cistern needs to come off. *cannot come earlier than 2:30

DESCRIPTION OF WORK PERFORMED:

I replaced the flush valve fill valve tank to bowl gasket tank holts, and supply line. Tested and in good working order

CHARGES. E. & O. E.

QTY.	CODE		DESCRIPTION		
1		Replace Toilet: FillValve, Flu	shValve Assembly, Tank Gasket, Tank Bolts, Supply Line	\$209.00	\$209.00
e	, G	warranty	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$209.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED RUISTED DETERIORATION OR LEAD PLIESS EVITURES CLEAN OUTS AND ANY OTHER DAMAGES.		\$10.45
					\$219.45
		we did. MADE THE MATERIAL			

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

Thank You!

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2015-10-16

CUSTOMER SIGNATURE

DATE