



DATE 2015-10-21	TECHNICIAN Darren Mann	JOB/ORDER # 5425	REFERENCE TEXT Client reference
FIRST NAME Mindy		LAST NAME Heslin	
BILLING ADDRESS COMPANY / BILLING NAME 419 WEST 23RD AVE VANCOUVER, V5Y2H5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 419 WEST 23RD AVE VANCOUVER, V5Y2H5 BRITISH COLUMBIA, CANADA	
PHONE 604.805.7757		EMAIL mindyheslin@gmail.com	

REASON FOR TODAY'S CALL:
 -crack in ABS drainage under kitchen sink. -seal in toilet to be replaced?

DESCRIPTION OF WORK PERFORMED:
 ---Kitchen Sink: Both slip joint adapters were cracked and leaking. I replaced a portion of the ABS drainage and tested by filling and draining both sides of the sink. ---
 Basement Toilet: I installed a customer supplied FlushValve gasket and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Re-Pipe ABS Drainage - Single Kitchen Sink	\$149.00	\$149.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$149.00
GST (5%):	\$7.45
TOTAL:	\$156.45

_____ 2015-10-21
 CUSTOMER SIGNATURE DATE