



HST #837181627

DATE 2015-11-02	TECHNICIAN Darren Mann		JOB/ORDER # 5471	REFERENCE TEXT Client reference		
FIRST NAME Elizabeth		LAST NAME Campbell				
BILLING ADDRESS COMPANY / BILLING NAME 1501 - 638 BEACH CRES VANCOUVER, V6Z3H4 BRITISH COLUMBIA, CANADA			1501 - 638 BEACH BUZZER: 3082 VANCOUVER, V6	SERVICE ADDRESS 1501 - 638 BEACH CRES BUZZER: 3082 VANCOUVER, V6Z3H4 BRITISH COLUMBIA, CANADA		
PHONE 604.765.8852			EMAIL Karenminato@yah	noo.com		

REASON FOR TODAY'S CALL: Shower not draining properly

DESCRIPTION OF WORK PERFORMED:

-I cleared hair from the shower drain using the PowerSpin drain snake.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1		Clean drain using Pov	werSpin / Tub	b/Shower	\$139.00	\$139.00
Gwe us Feedback WARRANTY:		ARRANTY: <u>F</u>	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00	
	Please visit our feedback page at:		<u>L</u>	<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$6.95
		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		TOTAL:	\$145.95	
			EREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY DE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2015-11-02 CUSTOMER SIGNATURE DATE