



DATE 2015-11-13	TECHNICIAN Darren Mann	JOB/ORDER # 5511	REFERENCE TEXT Client reference
FIRST NAME Ryan		LAST NAME McKinley	
BILLING ADDRESS COMPANY / BILLING NAME 867 HAMILTON ST VANCOUVER, V6B6B7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2202 - 867 HAMILTON ST BUZZER: 110 VANCOUVER, V6B6B7 BRITISH COLUMBIA, CANADA	
PHONE 6043401611		EMAIL ryan_mckinley@vancity.com	

REASON FOR TODAY'S CALL:  
 -install customer supplied gaburator. -cold side of guest lavatory making noise in some positions.

DESCRIPTION OF WORK PERFORMED:  
 -I installed the customer supplied garburator and tested by filling and draining the sink while running the garburator. -the cold shut off valve under the lavatory sink was half closed causing water hammering. I fully opened this valve.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Install Garburator - Customer Supplied	\$149.00	\$149.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL: \$149.00

GST (5%): \$7.45

**TOTAL: \$156.45**



2015-11-13

---

CUSTOMER SIGNATURE DATE