



DATE 2016-02-02	TECHNICIAN Darren Mann	JOB/ORDER # 5793	REFERENCE TEXT Client reference
FIRST NAME Barbara		LAST NAME Martinez	
BILLING ADDRESS COMPANY / BILLING NAME 419 - 1445 MARPOLE AVE VANCOUVER, V6H1S5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 703 - 501 PACIFIC ST VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.953.2153		EMAIL barbarabadulescu@gmail.com	

REASON FOR TODAY'S CALL:
Replace toilet fillvalve.

DESCRIPTION OF WORK PERFORMED:
-The toilet fillvalve was not functioning properly but I also noticed that the FlushValve was cracked. I replaced the toilet fillvalve, flushvalve assembly, flapper, tank to bowl gasket, tank bolts, and supply line.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		TOILT TANK REBUILD - STANDARD	\$199.00	\$199.00
SUBTOTAL:				\$199.00
GST (5%):				\$9.95
TOTAL:				\$208.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

Vainara

2016-02-02

 CUSTOMER SIGNATURE DATE