



DATE 2016-03-10	TECHNICIAN Darren Mann	JOB/ORDER # 5926	REFERENCE TEXT Client reference
FIRST NAME Lou		LAST NAME Guerrero	
BILLING ADDRESS COMPANY / BILLING NAME 663 EAST 14TH AVE VANCOUVER, V5T 2N2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 606 - 1255 SEYMOUR ST BUZ#704 ROBBIE(TENANT): 778.882.2436 VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA	
PHONE 604.218.7300		EMAIL louguerrero@shaw.ca	

REASON FOR TODAY'S CALL:
 Garburator not working , please text Robbie Gallagher 778-882-2436

DESCRIPTION OF WORK PERFORMED:
 The garburator grinding chamber was deteriorated quite badly, pieces of metal were flaking off which I believe is what caused it to seize up. There was also signs of leaking from the bottom of the garburator. I replaced the garburator with new and tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$309.00	\$309.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

_____ 2016-03-10

 CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$309.00
GST (5%):	\$15.45
TOTAL:	\$324.45