



DATE 2016-03-18	TECHNICIAN Darren Mann	JOB/ORDER # 5951	REFERENCE TEXT Client reference
FIRST NAME Aileen		LAST NAME Reinders	
BILLING ADDRESS 808 - 1009 EXPO BLVD VANCOUVER, V6Z 2V9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #808 - 1009 EXPO BLVD, BUZZER BUZZER 1653 VANCOUVER, V6Z 2V9 BRITISH COLUMBIA, CANADA	
PHONE 6047876189		EMAIL aileen.hua@gmail.com	

REASON FOR TODAY'S CALL:
garburator jammed leak under bathroom sink

DESCRIPTION OF WORK PERFORMED:
-The garburator grinding chamber plate had detached. I replaced the garburator with new and tested by filling and draining the sink multiple times. -The leak under the lavatory sink was coming from a slip joint connection. I added Teflon tape to the threads and re-tightened the slip joint adaptor. Tested by filling and draining the sink multiple times with no sign of moisture.


QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2016-03-18

CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
TOTAL:	\$292.95