



DATE 2016-05-16	TECHNICIAN Darren Mann	JOB/ORDER # 6163	REFERENCE TEXT Client reference
FIRST NAME John & Carroll		LAST NAME Davis	
BILLING ADDRESS COMPANY / BILLING NAME 1101 - 1501 HOWE ST VANCOUVER, BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1101 - 1501 HOWE ST, BUZZER 8080 CARROLL: 1.250.309.2736 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.559.1248		EMAIL jdavis@grossmanstanley.com	

REASON FOR TODAY'S CALL:
 -not getting any hot water from the kitchen faucet.

DESCRIPTION OF WORK PERFORMED:
 -The hot shut off valve under the kitchen faucet failed and bits of rubber were clogging up the supply line. I repaired the shut off valve by replacing the washer, stem, packing, packing nut, and handle. I then flushed the debris out of the hot supply line and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair 1/2" x 3/8" Angle or Straight Stop	\$139.00	\$139.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95

_____ 2016-05-16
 CUSTOMER SIGNATURE DATE