



DATE 2016-06-23	TECHNICIAN Darren Mann	JOB/ORDER # 6252	REFERENCE TEXT Client reference
FIRST NAME Jessica		LAST NAME Miskiewicz	
BILLING ADDRESS COMPANY / BILLING NAME 608 - 111 WEST GEORGIA ST VANCOUVER, BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 608 - 111 WEST GEORGIA ST VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.989.1902		EMAIL Miskiewicz85@yahoo.ca	

REASON FOR TODAY'S CALL:
garburator leaking?

DESCRIPTION OF WORK PERFORMED:

-The leaking was coming from the mounting bracket which I tightened to repair but during testing noticed the inside of the grinding chamber was deteriorating to the point that chunks of metal were breaking off. I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00
			SUBTOTAL:	\$279.00
			GST (5%):	\$13.95
			TOTAL:	\$292.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

_____ 2016-06-23
 CUSTOMER SIGNATURE DATE