



DATE 2016-07-14	TECHNICIAN Darren Mann	JOB/ORDER # 6305	REFERENCE TEXT Client reference
FIRST NAME Jason		LAST NAME Cheng	
BILLING ADDRESS COMPANY / BILLING NAME 610 GRANVILLE ST VANCOUVER, V6C3T3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1514 - 610 GRANVILLE ST BUZZER: #5180 VANCOUVER, V6C3T3 BRITISH COLUMBIA, CANADA	
PHONE 7788754871		EMAIL jason.cheng401.jc@gmail.com	

**REASON FOR TODAY'S CALL:**

It appears my sink is leaking from the garbarator but I am not certain. I see that it's quit rusted around the garbarator area. Would you be able to me take a peak at this and recommend a solution. Thanks.

**DESCRIPTION OF WORK PERFORMED:**

-I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

**WARRANTY:** **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-07-14

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
<b>TOTAL:</b>	<b>\$292.95</b>