



DATE 2016-08-24	TECHNICIAN Darren Mann	JOB/ORDER # 6420	REFERENCE TEXT Client reference
FIRST NAME Linda		LAST NAME Rainaldi	
BILLING ADDRESS COMPANY / BILLING NAME 1949 CREELMAN AVENUE VANCOUVER, V6J 1B8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1949 CREELMAN AVENUE VANCOUVER, V6J 1B8 BRITISH COLUMBIA, CANADA	
PHONE 604.723.5965		EMAIL ld.rain@telus.net	

REASON FOR TODAY'S CALL:
 Repair hose-bib isolating valve.

DESCRIPTION OF WORK PERFORMED:
 I found the main water shut off valve in the crawl space and repaired the hose-bib isolating valve(located near the HWT) by replacing the washer, stem, and nut. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair Shut Off Valve	\$149.00	\$149.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:		\$149.00
GST (5%):		\$7.45
TOTAL:		\$156.45

 _____ CUSTOMER SIGNATURE	2016-08-24 _____ DATE
---	-----------------------------