



DATE 2016-08-25	TECHNICIAN Darren Mann	JOB/ORDER # 6418	REFERENCE TEXT Client reference
FIRST NAME Jordon		LAST NAME Harco	
BILLING ADDRESS COMPANY / BILLING NAME 709 - 428 W 8TH AVE VANCOUVER, V5Y 1N9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 709 - 428 W 8TH AVE BUZZER: 114 VANCOUVER, V5Y 1N9 BRITISH COLUMBIA, CANADA	
PHONE 778.991.8551		EMAIL harcopolo@gmail.com	

REASON FOR TODAY'S CALL:

Both of the showers in my unit are not draining properly. The upstairs shower takes hours to drain completely after a shower, and the downstairs shower takes maybe 20 minutes to drain away.

DESCRIPTION OF WORK PERFORMED:


I cleaned both tub drains using the PowerSpin drain snake and tested by filling the tubs 6" and draining.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Quoted Price	\$179.00	\$179.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



_____ 2016-08-25

 CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$179.00
GST (5%):	\$8.95
TOTAL:	\$187.95