



DATE 2016-09-07	TECHNICIAN Darren Mann	JOB/ORDER # 6460	REFERENCE TEXT Client reference
FIRST NAME Lanna		LAST NAME Olson	
BILLING ADDRESS COMPANY / BILLING NAME 304 - 2015 TRAFALGAR ST VANCOUVER, V6K 3S5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS UNIT 304 - 2015 TRAFALGAR STREET BUZZER: 304 VANCOUVER, V6K 3S5 BRITISH COLUMBIA, CANADA	
PHONE 778.870.3711		EMAIL lannakolson@gmail.com	

REASON FOR TODAY'S CALL:
Garburator not functioning.

DESCRIPTION OF WORK PERFORMED:
The garburator was seized up due to rust buildup and bits of metal flaking off from the grinding chamber. I was able to free it up and tested by filling and draining the sink multiple times.

TECHNICIAN RECOMMENDATIONS:
Although the garburator is working and no leaks were detected I strongly recommend replacement of the garburator because it will likely jam up in the future due to the breaking down of the metal within the grinding chamber.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
SUBTOTAL:				\$109.00
GST (5%):				\$5.45
TOTAL:				\$114.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2016-09-07

 DATE