



DATE 2016-09-12	TECHNICIAN Darren Mann	JOB/ORDER # 6478	REFERENCE TEXT Client reference
FIRST NAME Craig	LAST NAME taylor		
BILLING ADDRESS COMPANY / BILLING NAME 907 BEACH AVE VANCOUVER, V6Z2R3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #504 - 907 BEACH AVE VANCOUVER, V6Z2R3 BRITISH COLUMBIA, CANADA	
PHONE 6047279528		EMAIL craigt2k@hotmail.com	

REASON FOR TODAY'S CALL:
 The top of the faucet has broken off the bathroom sink. The kitchen sink tap always comes loose, not sure if it can be fixed or needs to be replaced.

DESCRIPTION OF WORK PERFORMED:
 -I replaced the lavatory faucet with a new Delta single handel faucet and tested. -I tightened the nut that secures the kitchen faucet.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install Delta Lav Faucet - 536TPDST	\$239.00	\$239.00
SUBTOTAL:				\$239.00
GST (5%):				\$11.95
TOTAL:				\$250.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

_____ 2016-09-12

 CUSTOMER SIGNATURE DATE