



DATE 2016-09-22	TECHNICIAN Darren Mann	JOB/ORDER # 6525	REFERENCE TEXT Client reference
FIRST NAME Rita		LAST NAME Keeler	
BILLING ADDRESS COMPANY / BILLING NAME 104 - 2628 ASH ST VANCOUVER, V5Z 4L2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 104 - 2628 ASH ST, BUZZER 104 VANCOUVER, V5Z 4L2 BRITISH COLUMBIA, CANADA	
PHONE 604.266.1414		EMAIL keelerrio@shaw.ca	

REASON FOR TODAY'S CALL:
inspect shower 90

DESCRIPTION OF WORK PERFORMED:
-I removed the shower 90 and inspected the wingback 90 behind the tile. I did not see any sign of cracking. I then re-installed the shower 90 with a 1/2" X 1.5" brass nipple. The wingback 90 is not supported behind the tile so there is 1/4" of play but under normal use it should not move forward, if it does it just simply pushes back.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45

_____ 2016-09-22
 CUSTOMER SIGNATURE DATE