

HST #837181627

DATE 2016-09-23	TECHNICIAN Darren Mann		JOB/ORDER # 6533		REFERENCE TEXT Client reference	
FIRST NAME Mona		LAST NAME Erfani	97			
BILLING ADDRESS COMPANY / BILLING NAME 1206 - 1082 SEYMOUR ST VANCOUVER, V6B 1X9 BRITISH COLUMBIA, CANADA	A			SERVICE ADDRESS 1206 - 1082 SEYMOUR ST VANCOUVER, V6B 1X9 BRITISH COLUMBIA, CANADA	A	
PHONE 604.762.2895				EMAIL monamiu@gmail.com		

REASON FOR TODAY'S CALL:

garburator not working. *give 10 minutes heads up

DESCRIPTION OF WORK PERFORMED:

-The managed to free up the garburator and tested by filling and draining the sink multiple times while running the garburator. I did not remove anything out of the ordinary from the grinding chamber, it seemed to have been seized up due to rust. -I showed Mona how the garburator can be free'd up if it happens to seize up

QTY.	CODE	DESCRIPTION			PRICE
1		Labour		\$109.00	\$109.00
invoice and tell us how we did. MADE THAM MATERIALS SETTLED, I RESULTING TERMS: NE		and a du	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$114.45
			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE