



DATE 2016-09-30	TECHNICIAN Darren Mann	JOB/ORDER # 6565	REFERENCE TEXT Client reference
FIRST NAME Kazusa		LAST NAME Sawahata	
BILLING ADDRESS COMPANY / BILLING NAME 1003 - 1088 RICHARDS ST VANCOUVER, V6B 0J8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1003 - 1088 RICHARDS STREET SASAN(TENANT): 778.898.2820 BUZZER: 5172 VANCOUVER, V6B 0J8 BRITISH COLUMBIA, CANADA	
PHONE 604.683.8052		EMAIL sawahakazu@hotmail.com	

REASON FOR TODAY'S CALL:  
Garburator is stuck? Not working.

DESCRIPTION OF WORK PERFORMED:  
The garburator was jammed up due to broken glass. I removed a dozen or so small pieces of glass from the grinding chamber and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

**WARRANTY:** **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
<b>TOTAL:</b>	<b>\$114.45</b>

\_\_\_\_\_ 2016-09-30  
 CUSTOMER SIGNATURE DATE