



DATE 2016-10-13	TECHNICIAN Darren Mann	JOB/ORDER # 6587	REFERENCE TEXT Client reference
FIRST NAME Elena		LAST NAME Demelo	
BILLING ADDRESS COMPANY / BILLING NAME 1603 - 989 BEATTY ST VANCOUVER, V6Z 3C2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1603 - 989 BEATTY STREET BUZZER: 2603 VANCOUVER, V6Z 3C2 BRITISH COLUMBIA, CANADA	
PHONE 778-998-8984		EMAIL elenap123@hotmail.com	

REASON FOR TODAY'S CALL:
garburator jammed, sink not draining.

DESCRIPTION OF WORK PERFORMED:
I unjammed the garburator and tested by filling and draining the sink multiple times while running the garburator. *nothing was pulled out of the grinding chamber, whatever caused it to seize up was flushed through.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-10-13

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45