

2016-10-20

DATE

HST #837181627

DATE 2016-10-20	TECHNICIAN Darren Mann		JOB/ORDER # 6622	REFERENCE TEXT Client reference
FIRST NAME John		LAST NAME Harrison		
BILLING ADDRESS COMPANY / BILLING NAME 601 - 499 BROUGHTON ST VANCOUVER, V6G3K1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 601 - 499 BROUGHTON ST BUZZER: 1219 VANCOUVER, V6G3K1 BRITISH COLUMBIA, CANADA	
PHONE 604.219.1618			EMAIL johnhar@telus.net)- / ·

REASON FOR TODAY'S CALL:

Bathroom toilet(American Standard) is leaking water into toilet after it fills.

DESCRIPTION OF WORK PERFORMED:

I replaced the toilet FillValve, flapper, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1	//	Replace Toilet FillValve, Flapper, Supply - Standard			\$169.00	\$169.00
L ine	, 115 F	eedhack	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
Gwe us Feedback Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		GST (5%):	\$8.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$177.45		
Thank You!		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.				

CUSTOMER SIGNATURE