



DATE 2016-10-25	TECHNICIAN Darren Mann	JOB/ORDER # 6377	REFERENCE TEXT Client reference
FIRST NAME Roger		LAST NAME Lafrenière	
BILLING ADDRESS COMPANY / BILLING NAME 590 NICOLA STREET VANCOUVER, V6G 3J8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #901 - 590 NICOLA STREET, BUZZER 1038 VANCOUVER, V6G 3J8 BRITISH COLUMBIA, CANADA	
PHONE 778-836-7435		EMAIL rogerlafreniere@shaw.ca	

REASON FOR TODAY'S CALL:
lav faucet still leaking.

DESCRIPTION OF WORK PERFORMED:

On July 28 I made a visit to replace the water filtration tap and replace the cartridge within a dripping lavatory faucet. After replacing the cartridge within the lav faucet the dripping persisted. I contacted a Grohe customer support and they suggested replacing the seat within the faucet body. ---Oct 25: I received the new seat (part#00913131), installed and tested. The issue with dripping seems to have been resolved.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
			SUBTOTAL:	\$109.00
			GST (5%):	\$5.45
			TOTAL:	\$114.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-10-25

CUSTOMER SIGNATURE

DATE