



DATE 2016-11-07	TECHNICIAN Darren Mann	JOB/ORDER # 6678	REFERENCE TEXT Client reference
FIRST NAME Peggy		LAST NAME Gouin	
BILLING ADDRESS COMPANY / BILLING NAME 2400 - 590 NICOLA ST VANCOUVER, V6G 3J8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2400 - 590 NICOLA STREET BUZZER: 1116 VANCOUVER, V6G 3J8 BRITISH COLUMBIA, CANADA	
PHONE 780.974.0453		EMAIL peggygouin@icloud.com	

REASON FOR TODAY'S CALL:
Master Bathroom: Shower not draining.

DESCRIPTION OF WORK PERFORMED:
-I used the PowerSpin drain snake to clean hair from the shower drain and tested. -Peggy mentioned while onsite that the shower head in the shower was losing pressure. I removed the shower head but there was no debris at the entrance of the head. I suggest replacement of the head.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	\$149.00	\$149.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL: \$149.00
 GST (5%): \$7.45
 TOTAL: \$156.45

PCG

CUSTOMER SIGNATURE
DATE

2016-11-07