

HST #837181627

DATE 2017-01-18	TECHNICIAN Darren Mann		JOB/ORDER # 6916		REFERENCE TEXT Client reference
FIRST NAME Stephanie		LAST NAME Parker	7		
BILLING ADDRESS COMPANY / BILLING NAME 2905 - 111 WEST GEORGIA ST VANCOUVER, V6B1T8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2905 - 111 WEST GEORGIA ST VANCOUVER, V6B1T8 BRITISH COLUMBIA, CANADA	
PHONE 778.846.7218				EMAIL s.parker0318@gmail.com	

REASON FOR TODAY'S CALL:

The toilet has an issue with the float and refilling the tank. Something in there is leaking. It takes about a half hour to fill once flushed and hisses while it does.

DESCRIPTION OF WORK PERFORMED:

The FillValve was malfunctioning, taking a very long time to refill the tank after a flush. I replaced the FillValve and supply line and tested.

QTY.	CODE	DESCRIPTION					PRICE
1		Replace toilet FillValve - standard					\$159.00
emo		bed hack	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$159.00
Guve us Geedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MAD	IADE, ABSOLUTELY NO	GST (5%):	\$7.95	
		INTEREST A	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		TOTAL:	\$166.95	
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.					
				CUSTOMER SIGNATURE	2017-01-18 DATE		