

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-02-17	TECHNICIAN Darren Mann		JOB/ORDER # 7007		REFERENCE TEXT Client reference
FIRST NAME Patrick		LAST NAME Crandall	7		
BILLING ADDRESS COMPANY / BILLING NAME 803 - 989 RICHARDS ST VANCOUVER, V6B6R6 BRITISH COLUMBIA, CANADA		\sim	4	SERVICE ADDRESS 803 - 989 RICHARDS ST , BUZ BUZ#0830 VANCOUVER, V6B6R6 BRITISH COLUMBIA, CANADA	
PHONE 778-792-9671	-			EMAIL pmc200k@outlook.com	

REASON FOR TODAY'S CALL:

Toilet in 2nd bathroom hasn't been used in a while. Now when it flushes, too much water spills out the bowl and onto the floor.

DESCRIPTION OF WORK PERFORMED:

I tested the toilet by flushing large rolled up balls of toilet paper and it did not clog. I did however notice that water was leaking out between the tank and the bowl during each flush. I removed the tank and reinstalled with a new tank to bowl gasket, tank bolts, and supply line. Tested and in good working order.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Replace Tank To Bowl Gasket - Standard					\$169.00
Guve us Geedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		and a du	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$169.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	DT MADE, ABSOLUTELY NO	GST (5%):	\$8.45	
		INTEREST AT			TOTAL:	\$177.45	
		SETTLED, RUS RESULTING F	ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS A ROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATE & O. E. CUSTOMER SIGNATURE				