



DATE 2017-02-17	TECHNICIAN Darren Mann	JOB/ORDER # 7015	REFERENCE TEXT Client reference
FIRST NAME Christopher		LAST NAME George	
BILLING ADDRESS COMPANY / BILLING NAME 155 BOATHOUSE MEWS VANCOUVER, V6Z2Z9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 155 BOATHOUSE MEWS VANCOUVER, V6Z2Z9 BRITISH COLUMBIA, CANADA	
PHONE 3475793220		EMAIL cg802@yahoo.com	

REASON FOR TODAY'S CALL:

Hi, I unscrewed the P trap to our bathroom sink faucet to clean it out a bit, and it seems like there was a connector piece soldered onto the top part which has come off. We may need a new connector piece, but i'm unsure. Thanks!

DESCRIPTION OF WORK PERFORMED:

The threads of the tailpiece snapped off inside the drain body. I replaced the drain with a pop-up style drain and tested by filling and draining the sink multiple times.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Lav Drain - Pop-Up	\$169.00	\$169.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$169.00
GST (5%):	\$8.45
TOTAL:	\$177.45



 CUSTOMER SIGNATURE

2017-02-17

 DATE