



DATE 2017-02-21	TECHNICIAN Darren Mann	JOB/ORDER # 7028	REFERENCE TEXT Client reference
FIRST NAME Laura-Lee		LAST NAME Armstrong	
BILLING ADDRESS COMPANY / BILLING NAME #902 - 628 KINGHORNE MEWS VANCOUVER, BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #902 - 628 KINGHORNE MEWS , BUZZER #6031 LAUREN ARMSTRONG:778.989.6704 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.644.0781		EMAIL llarmstrong@agroup.ca	

REASON FOR TODAY'S CALL:
3 toilets having issues

DESCRIPTION OF WORK PERFORMED:
-The guest bathroom and powder room toilets were clogged and affecting each other. When one was flushed the other would bubble up. I was able to clear the blockage and tested by flushing large rolled up balls of toilet paper. -The master bathroom toilet seems to be flushing normally.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clear toilet blockage using 6' toilet auger	\$139.00	\$139.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

_____ 2017-02-21

 CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95