



DATE 2017-02-22	TECHNICIAN Darren Mann	JOB/ORDER # 7029	REFERENCE TEXT Client reference
FIRST NAME Luiz	LAST NAME Moreira		
BILLING ADDRESS COMPANY / BILLING NAME 413 - 77 WALTER HARDWICK AVE. VANCOUVER, V5Y0C6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 413 - 77 WALTER HARDWICK AVE., BUZZER 3413 VANCOUVER, V5Y0C6 BRITISH COLUMBIA, CANADA	
PHONE 778.580.6721		EMAIL luizrpm@hotmail.com	

REASON FOR TODAY'S CALL:

I'm having a problem with my Kohler toilet, there is water leaking from the tank into the bowl and the tank keeps filling up every once in a while.

DESCRIPTION OF WORK PERFORMED:

The flushvalve gasket had bubbles forming on it, not allowing it to make a proper seal. I replaced the flushvalve gasket and tested. Toilet is in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard FlushValve Gasket - DISCOUNTED	\$109.00	\$109.00
			SUBTOTAL:	\$109.00
			GST (5%):	\$5.45
			TOTAL:	\$114.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2017-02-22

CUSTOMER SIGNATURE

DATE