



DATE 2017-03-31	TECHNICIAN Darren Mann	JOB/ORDER # 7158	REFERENCE TEXT Client reference
FIRST NAME Susan		LAST NAME Ackerman	
BILLING ADDRESS 423 - 610 GRANVILLE ST VANCOUVER, V6C3T3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 423 - 610 GRANVILLE ST VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 1.438.491.8091		EMAIL nicolas.morant@corporatestays.com	

REASON FOR TODAY'S CALL:  
garburator not working

DESCRIPTION OF WORK PERFORMED:  
I was able to free up the garburator but during testing noticed that the grinding chamber was starting to deteriorate quiet badly, causing bits of metal to break off. I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
TOTAL:	\$292.95

\_\_\_\_\_ 2017-03-31  
 CUSTOMER SIGNATURE DATE