



DATE 2017-05-29	TECHNICIAN Darren Mann	JOB/ORDER # 7328	REFERENCE TEXT Client reference
FIRST NAME Joana		LAST NAME Ho	
BILLING ADDRESS COMPANY / BILLING NAME 908 - 888 HAMILTON ST VANCOUVER, V6B5W4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 908 - 888 HAMILTON ST VANCOUVER, V6B5W4 BRITISH COLUMBIA, CANADA	
PHONE 778.990.7708		EMAIL joanaho1215@gmail.com	

REASON FOR TODAY'S CALL:  
toilet not flushing well

DESCRIPTION OF WORK PERFORMED:  
I cleared the toilet blockage using the 6' toilet auger and tested by flushing large rolled up balls of toilet paper. Nothing was pulled out of the toilet, whatever caused the blockage was pushed through and flushed away.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clear toilet blockage using 6' toilet auger	\$139.00	\$139.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**


WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:		\$139.00
GST (5%):		\$6.95
TOTAL:		\$145.95

 <hr/> CUSTOMER SIGNATURE	2017-05-29 <hr/> DATE
---	--------------------------