



DATE 2017-06-27	TECHNICIAN Darren Mann	JOB/ORDER # 7438	REFERENCE TEXT Client reference
FIRST NAME Mike	LAST NAME McCaig		
BILLING ADDRESS COMPANY / BILLING NAME 303 - 1888 ALBERNI ST VANCOUVER, V6G 1B3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 303 - 1888 ALBERNI ST, BUZZER 114 VANCOUVER, V6G 1B3 BRITISH COLUMBIA, CANADA	
PHONE 604.689.1057		EMAIL mikenbill@telus.net	

REASON FOR TODAY'S CALL:
shower trim not attached.

DESCRIPTION OF WORK PERFORMED:
 ---June27: I made a visit and found the trim to be broken. ---July11: I installed a new valve cover to allow for the attachment of a Grohe trim kit. I replaced the shower valve cartridge(Tempress ii) and installed the new Grohe trim. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$247.50	\$247.50
1		Grohe Eurosmart Cosmopolitan	\$120.00	\$120.00
1		Grohe Valve Cover	\$110.00	\$110.00
1		Tempress ii Cartridge	\$95.00	\$95.00

SUBTOTAL:	\$572.50
GST (5%):	\$28.63
TOTAL:	\$601.13

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2017-06-27

CUSTOMER SIGNATURE

DATE