



DATE 2017-07-12	TECHNICIAN Darren Mann	JOB/ORDER # 7502	REFERENCE TEXT Client reference
FIRST NAME Vera		LAST NAME Sal	
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B 2T4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2803 - 565 SMITHE ST KEYS AT OFFICE. TENANT BACK IN THE AFTERNOON VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.980.9100		EMAIL vera@rentitfurnished.com	

REASON FOR TODAY'S CALL:
 Garburator: looks like a piece of blade rusted and broke off and is spinning around.

DESCRIPTION OF WORK PERFORMED:
 There was a bottle cap in the grinding chamber. I removed the bottle cap and got the garburator working again but during testing noticed it was leaking from the bottom. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$319.00	\$319.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

_____ 2017-07-12

 CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$319.00
GST (5%):	\$15.95
TOTAL:	\$334.95