



DATE 2017-07-31	TECHNICIAN Darren Mann	JOB/ORDER # 7515	REFERENCE TEXT Client reference
FIRST NAME Raeann		LAST NAME Dienstag	
BILLING ADDRESS COMPANY / BILLING NAME 501 - 1225 BARCLAY ST VANCOUVER , V6E 1H5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 501 - 1225 BARCLAY ST VANCOUVER , V6E 1H5 BRITISH COLUMBIA, CANADA	
PHONE 33674625997		EMAIL Raeann66@me.com	

REASON FOR TODAY'S CALL:  
No cold water in one of my showers

DESCRIPTION OF WORK PERFORMED:  
 ---July31: I replaced the mixing cartridge but the issue persists. The shower valve is a Moentrol and there is a separate pressure balance cartridge that I believe is causing the issue. ---Aug1: I purchased and installed a new Moentrol Pressure Balancing Spool. tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
2		Discount Labour	\$99.00	\$198.00
1		Moentrol PBS 1423	\$110.00	\$110.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$308.00
GST (5%):	\$15.40
TOTAL:	\$323.40

\_\_\_\_\_ 2017-07-31  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE DATE