



DATE 2017-08-25	TECHNICIAN Darren Mann	JOB/ORDER # 7642	REFERENCE TEXT Client reference
FIRST NAME Easyrent		LAST NAME Admin	
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 3009 - 833 SEYMOUR ST CARLI: 604.817.6570 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.662.3279		EMAIL info@easyrent.ca	

REASON FOR TODAY'S CALL:
kitchen sink draining slowly. *grab keys from Easyrent.

DESCRIPTION OF WORK PERFORMED:
The garburator grinding chamber had deteriorated to the point that chunks of metal were flaking off and jamming the garburator. I replaced the garburator with a new Waste King 1001 and tested by filling the sink 6" and draining multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 2600 Garburator	\$299.00	\$299.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$299.00
GST (5%):	\$14.95
TOTAL:	\$313.95

_____ 2017-08-25

 CUSTOMER SIGNATURE DATE