



DATE 2017-09-07	TECHNICIAN Darren Mann	JOB/ORDER # 7676	REFERENCE TEXT Client reference
FIRST NAME Colleen		LAST NAME Wickenheiser	
BILLING ADDRESS COMPANY / BILLING NAME 211 - 2080 MAPLE ST VANCOUVER, V6J 4P9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 211 - 2080 MAPLE ST BUZ: 360 VANCOUVER, V6J 4P9 BRITISH COLUMBIA, CANADA	
PHONE 604.731.3589		EMAIL colleen.a.w@shaw.ca	

REASON FOR TODAY'S CALL:

I have a small leak around a screw at the bottom of my toilet. I think I simply need a new washer and the base needs to be tightened.

DESCRIPTION OF WORK PERFORMED:

I was able to stop the leak from the tank bolt by tightening the nut that secures it. During testing I noticed the toilet was not fully secure to the floor and it leaked when flushed. I removed the toilet and reinstalled with a new wax ring, supply line, and tee bolts. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet Wax Seal - Standard	\$189.00	\$189.00
			SUBTOTAL:	\$189.00
			GST (5%):	\$9.45
			TOTAL:	\$198.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2017-09-07

CUSTOMER SIGNATURE

DATE