

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-10-31	TECHNICIAN Darren Mann		JOB/O 7879	RDER #	REFERENCE TEXT Client reference
FIRST NAME Fayyaz		LAST NAME Karmali	7		
BILLING ADDRESS COMPANY / BILLING NAME 16C - 139 DRAKE ST VANCOUVER, V6Z 2T7 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 16C - 139 DRAKE STREET BUZZER: 865 VANCOUVER, V6Z 2T7 BRITISH COLUMBIA, CANADA	
PHONE 604.773.9571				EMAIL fayyaz.karmali@gmail.com	

REASON FOR TODAY'S CALL:

Toilet in guest bathroom is clogged. Rainshower in master bathrooms squeals when first turned on and then a few minutes after being turned off it leaks a bit.

DESCRIPTION OF WORK PERFORMED:

-I used the 6? toilet auger to clear the toilet blockage. Tested by flushing large rolled up balls of toilet paper. -The squeeling noise that occurs for a few seconds when the master ensuite rain shower is activated appears to be coming from the diverter valve, not the head itself. The manufacturer will have to be contacted to inquire about a possible part replacement.

	Clear toilet blockage using 6' t	oilet auger		\$139.00	\$139.00
		Clear toilet blockage using 6' toilet auger			
Gwe us Fe	WARRANTY:	NARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAY MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABS		SUBTOTAL:	\$139.00
Please visit our feedback p				GST (5%):	\$6.95
www.yaletownplumbing.co	from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$145.95	
invoice and tell us how we	MATERIALS	F SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND TH. S LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESF KUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS A S FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. T CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATER E. & O. E.	PONSIBLE FOR BROKEN, ND ANY OTHER DAMAGES		