



DATE 2017-12-06	TECHNICIAN Darren Mann	JOB/ORDER # 7988	REFERENCE TEXT Client reference
FIRST NAME Dean		LAST NAME Davis	
BILLING ADDRESS COMPANY / BILLING NAME 1903 - 1225 RICHARDS ST VANCOUVER, V6B 1E6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1903 - 1225 RICHARDS STREET BUZZER: 2903 VANCOUVER, V6B 1E6 BRITISH COLUMBIA, CANADA	
PHONE 1.403.305.7723		EMAIL deanjdavis@outlook.com	

REASON FOR TODAY'S CALL:

Garburator stopped working. Nothing happens when I turn on the power. There is no sound, no movement. I reset the breaker and that did not help.

DESCRIPTION OF WORK PERFORMED:

The garburator grinding chamber had deteriorated to the point that bits of metal were breaking off. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
TOTAL:	\$292.95

_____ 2017-12-06
 CUSTOMER SIGNATURE DATE