



DATE 2017-12-06	TECHNICIAN Darren Mann	JOB/ORDER # 8002	REFERENCE TEXT Client reference
FIRST NAME Hossein	LAST NAME Malek		
BILLING ADDRESS COMPANY / BILLING NAME 2596 PALMERSTON AVE WEST VANCOUVER, V7V2W5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1303 - 1055 HOMER ST NICOLE: 778.988.7706 BUZ#1414 WEST VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.926.3232	EMAIL hossein.malek@gmail.com		

REASON FOR TODAY'S CALL:
Garburator Leaking. Leak under bathroom sink.

DESCRIPTION OF WORK PERFORMED:
-The garburator grinding chamber had deteriorated to the point that bits of metal were breaking off. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator. -The leak under the bathroom sink was coming from the drain stopper lift rod. I tightened the nut that secures the lever rod and tested. No other leaks detected.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00
SUBTOTAL:				\$279.00
GST (5%):				\$13.95
TOTAL:				\$292.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

 CUSTOMER SIGNATURE

2017-12-06

 DATE