

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

## HST #837181627

DATE 2018-01-09	TECHNICIAN Darren Mann		JOB/ORDER # 8079		REFERENCE TEXT Client reference
FIRST NAME Mark		LAST NAME Woods	7		
BILLING ADDRESS COMPANY / BILLING NAME 1002 - 2077 NELSON ST VANCOUVER, V6G2Y2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1002 - 2077 NELSON ST, BUZZ VANCOUVER, V6G2Y2 BRITISH COLUMBIA, CANADA	
PHONE 1.236.868.2020				EMAIL markowoods@hotmail.com	

REASON FOR TODAY'S CALL:

My kitchen faucet has been leaking for a while via the stem. Assume it was a broken washer or o-ring. Now the whole stem pops out when the water is turned on (see detail in picture). Not sure if it can be repaired or needs a complete replacement. Expert advice, quote and appointment is appreciated!

## DESCRIPTION OF WORK PERFORMED:

I was able to stop the leaking by replacing orings within the faucet stem. Tested and in good working order.

QTY.	CODE	DESCRIPTION					PRICE
1		Labour	7			\$109.00	\$109.00
Guve us Geedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	SUBTOTAL:	\$109.00		
					GST (5%):	\$5.45	
		INTEREST AT		DGEMENT IS HEREBY	TOTAL:	\$114.45	
		MATERIALS L SETTLED, RU RESULTING F	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT I ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPON STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIAI & O. E.				