



DATE 2018-01-17	TECHNICIAN Darren Mann	JOB/ORDER # 8022	REFERENCE TEXT Client reference
FIRST NAME Amanda		LAST NAME Huizing	
BILLING ADDRESS COMPANY / BILLING NAME 501 PACIFIC ST VANCOUVER, V6E2X6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #2108 - 501 PACIFIC ST, BUZZER 166 VANCOUVER, V6E2X6 BRITISH COLUMBIA, CANADA	
PHONE 604.855.8278		EMAIL amandahuizing@gmail.com	

REASON FOR TODAY'S CALL:
 Bathtub drain is not draining. It's always been a little bit slow, but all of a sudden it has completely stopped draining.


DESCRIPTION OF WORK PERFORMED:
 I used the PowerSpin drain snake to clear hair from the tub drain. Tested by filling the tub 8? and draining.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	\$139.00	\$139.00
SUBTOTAL:				\$139.00
GST (5%):				\$6.95
TOTAL:				\$145.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2018-01-17

 DATE