



DATE 2018-03-01	TECHNICIAN Darren Mann	JOB/ORDER # 8246	REFERENCE TEXT Client reference
FIRST NAME natalie		LAST NAME leskinen	
BILLING ADDRESS COMPANY / BILLING NAME 407 - 488 HELMCKEN ST VANCOUVER, V6B6E4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 407 - 488 HELMCKEN ST, BUZZER #047 VANCOUVER, V6B6E4 BRITISH COLUMBIA, CANADA	
PHONE 604-506-3480		EMAIL natalieleskinen@hotmail.com	

REASON FOR TODAY'S CALL:
clean tub drain

DESCRIPTION OF WORK PERFORMED:
I used the PowerSpin drain snake to clear the tub drain and tested.

TECHNICIAN RECOMMENDATIONS:
*The tub drain is missing cross hairs which makes it possible for hard objects to slip though into the drainage below, and the drain overflow cap is starting to bend. I suggest replacing the tub drain trim. *The Toilet is not secured to the floor and has been moving. The toilet should be lifted and re-set with a new wax seal.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	\$139.00	\$139.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2018-03-01

CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95