



DATE 2018-03-09	TECHNICIAN Darren Mann	JOB/ORDER # 8275	REFERENCE TEXT Client reference
FIRST NAME Vikram		LAST NAME Beesam	
BILLING ADDRESS COMPANY / BILLING NAME 1701 - 1028 BARCLAY ST VANCOUVER, V6E0B1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1701 - 1028 BARCLAY ST #0108 VANCOUVER, V6E0B1 BRITISH COLUMBIA, CANADA	
PHONE 778.681.0695		EMAIL vikramsimha.lenovo@gmail.com	

REASON FOR TODAY'S CALL:
 our bathtub has issue. Water is not draining fast. Looks like it might have got clogged with hair. I tried liquid to clear but it did not help. Most probably you just need to bring the plumber's snake and remove the clog. It should not take much time. Let us know the quotation details.

DESCRIPTION OF WORK PERFORMED:
 I used the PowerSpin drain snake to clear hair from the tub drain.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	\$139.00	\$139.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-03-09

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95