



DATE 2018-04-25	TECHNICIAN Darren Mann	JOB/ORDER # 8392	REFERENCE TEXT Client reference
FIRST NAME Andrew		LAST NAME Frazer	
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B2T4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 403 - 1252 HORNBY ST. BUZ#3736 GEOFF: 778-980-4891 LOTUSCUSTOMCABINETS@GMAIL.COM VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.980.0141		EMAIL PMVan2@rentitfurnished.com	

REASON FOR TODAY'S CALL:
garburator not working.

DESCRIPTION OF WORK PERFORMED:
The garburator grinding chamber had deteriorated to the point that bits of metal were flaking off. I replaced the garburator with new and tested.

TECHNICIAN RECOMMENDATIONS:
During testing I noticed the undermount sink is not attached properly to the underside of the countertop. This will have to be cleaned, resiliconed, and secured using metal L-brackets.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00
			SUBTOTAL:	\$279.00
			GST (5%):	\$13.95
			TOTAL:	\$292.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

 CUSTOMER SIGNATURE

2018-04-25

 DATE