



DATE 2018-04-25	TECHNICIAN Darren Mann	JOB/ORDER # 8408	REFERENCE TEXT Client reference
FIRST NAME Kim	LAST NAME Hiebert		
BILLING ADDRESS COMPANY / BILLING NAME 2502 - 1009 EXPO BLVD VANCOUVER, V6Z 2V9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2502 - 1009 EXPO BLVD VANCOUVER, V6Z 2V9 BRITISH COLUMBIA, CANADA	
PHONE 778.240.2039		EMAIL kimrh@shaw.ca	

REASON FOR TODAY'S CALL:
 Bathtub not draining properly because plug mechanism has broken off.

DESCRIPTION OF WORK PERFORMED:
 I was able to remove the tub drain stopper lift rod and used the PowerSpin drain snake to clean the tub drain. Tested by filling the tub 6? and draining.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	\$139.00	\$139.00
SUBTOTAL:				\$139.00
GST (5%):				\$6.95
TOTAL:				\$145.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

_____ 2018-04-25 _____
 CUSTOMER SIGNATURE DATE