



2018-01-02

DATE

HST #837181627

DATE 2018-01-02	TECHNICIAN Darren Mann		JOB/ORDER # 8057		REFERENCE TEXT Client reference
FIRST NAME Nicole		LAST NAME Salvian	97		
BILLING ADDRESS COMPANY / BILLING NAME 1807 - 583 BEACH CR VANCOUVER, V6Z3E6 BRITISH COLUMBIA, CANADA		- 19	4	SERVICE ADDRESS 1807 - 583 BEACH CR, BUZZE VANCOUVER, V6Z3E6 BRITISH COLUMBIA, CANADA	
PHONE 604.217.7604				EMAIL nicolesalvian@hotmail.com	

REASON FOR TODAY'S CALL:

Leak under the sink caused by both hot and cold taps.

DESCRIPTION OF WORK PERFORMED:

The leak was coming from the connection between the left sink strainer assembly and the slip joint. I cut the ABS, installed a fernco coupling, and reattached. Tested

QTY.	CODE		UNIT PRICE	PRICE	
1	//	Discount Labour		\$99.00	\$99.00
0	(1	endlady	VARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
	Gwe us Feedback lease visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE