



DATE 2018-05-22	TECHNICIAN Darren Mann	JOB/ORDER # 8491	REFERENCE TEXT Client reference
FIRST NAME Elaine		LAST NAME Jensen	
BILLING ADDRESS COMPANY / BILLING NAME 925 WEST 8TH AVE VANCOUVER, V5Z1E4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #201 - 925 WEST 8TH AVE, BUZZER 201 VANCOUVER, V5Z1E4 BRITISH COLUMBIA, CANADA	
PHONE 604.729.6021		EMAIL mejens@shaw.ca	

REASON FOR TODAY'S CALL:  
toilet leaking at base when flushed

DESCRIPTION OF WORK PERFORMED:  
I lifted the toilet and found the wax seal to be broken. I re-set the toilet with a new MaxWax wax seal and braided supply line. I also noticed a small leak coming from the left tank bolt. I was able to tighten both right and left tank bolts another full turn. Tested and no other leaks detected.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet Wax Seal - Standard	\$189.00	\$189.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-05-22

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$189.00
GST (5%):	\$9.45
TOTAL:	\$198.45