

DATE 2018-06-04	TECHNICIAN Darren Mann	JOB/ORDER # 8529	REFERENCE TEXT Client reference
FIRST NAME Yuji	LAST NAME Kim		
BILLING ADDRESS COMPANY / BILLING NAME 2201 - 1277 MELVILLE ST VANCOUVER, V6E0A4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2201 - 1277 MELVILLE ST BUZZER: 5038 VANCOUVER, V6E0A4 BRITISH COLUMBIA, CANADA	
PHONE 778.866.6703	EMAIL minosmilk@hotmail.com		

REASON FOR TODAY'S CALL:
Hi, Garburator in the kitchen does not work well. I guess it is completely out of control.

DESCRIPTION OF WORK PERFORMED:
I was able to unjam the garburator by removing a few pieces of what altered to be thick metal foil. Tested by filling the sink 4? and draining multiple times while running the garburator. The garburator is in good working order with no signs of leaking.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:		\$109.00
GST (5%):		\$5.45
TOTAL:		\$114.45

 <hr/> CUSTOMER SIGNATURE	2018-06-04 <hr/> DATE
---	--------------------------